



Cable Corrosion Fix



THE AN/PSC-11 SINGLE CHANNEL, ANTI-JAM, MAN-PORTABLE (SCAMP) RADIO SET HAS A CABLE CORROSION PROBLEM.

FIVE CABLES ARE BEING REPLACED. THEY ARE...

Cable	NSN 5995-01-446-	
IU-VAA, W2	1469	
IU-SIP, W3	8583	
PLGR, W11	2573	
IU-LCU, W12	8586	
IU-TTA, W14	8576	

"IF YOUR SCAMP CABLES HAVE A **YELLOW BAND** ON THEM, THEY HAVE ALREADY BEEN REPLACED AND ARE GOOD TO GO."

"IF THEY **DON'T** HAVE THE YELLOW BAND, REPLACE THEM BY CALLING ROCKWELL COLLINS AT THEIR TOLL-FREE WARRANTY HOTLINE, (800) 797-8429, AND REQUESTING A DIRECT EXCHANGE. THEN FOLLOW ROCKWELL'S INSTRUCTIONS."

FOR **MORE** INFORMATION ON THE CABLES, THE CORROSION PROBLEM AND HOW TO REPLACE THEM, CONTACT CECOM, DSN 992-9175 OR (732) 532- 9175.

OR E-MAIL THEM AT:
naim.rizk@mail1.monmouth.army.mil

